


DC Preservation League
Annual Membership Meeting
The Old Post Office







Building History and Analysis



Image from the National Archives and HSR



1902 Registry Division Room Image from the National Archives and HSR








Main Sorting Room Image from the Library of Congress and HSR









The IRS Building to the east is under construction



1934-1967









1971- Image from the DCPL and HSR









Beyer Blinder








Image courtesy of Carol Highsmith


Beyer Blinde Belle















IRS and Ariel Rios Building





























Proposed Program

Guest Room
Retail/Restaurant
Bar/ Lounge
Meeting/ Conference Room
Pre-Function
Restrooms
National Park Service/ Museum
Support
Spa/Fitness








Lower Level


First Floor


Mezzanine

Proposed Program

Guest Room
Retail/Restaurant
Bar/ Lounge
Meeting/ Conference Room
Pre-Function
Restrooms
National Park Service/ Museum
Support
Spa/Fitness







Typical (Fourth) Floor

Fifth Floor

Ninth Floor

